	Manasquan Board of Education Lead in Water Results of Analysis			
School	Sample Location	First Draw Results	Second Draw Results	Remedial Response
				Replace Fixture and
High School	Water Chiller Fountain in First Floor Hall adjacent to Room 468	22.7	N/A	Supply Piping
				Replace Fixture and
High School	Water Chiller Fountain in Second Floor Hall adjacent to Room 570	40.8	N/A	Supply Piping
				Install Sign
				"Handwashing Only,
				No Drinking or
Elementary School	Kitchen Ceramic Sink (Closest Outlet to Point Of Entry)	23.3	1.4	Cooking
				Replace Fixture and
Elementary School	Kitchen Sink Faucet at Dish Wash Station	170	10.1	Supply Piping
				Replace Fixture and
Elementary School	Sink Faucet in Room 104	43.1	1.28	Supply Piping
				Replace Fixture and
Elementary School	Sink Faucet in Room 106	35	<1.00	Supply Piping
				Replace Fixture and
Elementary School	Sink Faucet in Room 108	38.2	11.2	Supply Piping
				Replace Fixture and
Elementary School	Sink Faucet in Room 110	21.9	<1.00	Supply Piping
				Replace Fixture and
Elementary School	Water Chiller Fountain in Cafetorium	20.5	N/A	Supply Piping
				Replace Fixture and
Elementary School	Water Chiller Fountain in Gymnasium adjacent to Girls Locker Room	16.6	N/A	Supply Piping

